PROJECT: SAMS
ASS'Y MOMENCIATURE: END EFFECTOR

SYSTEM: NECHANICAL ARM SUBSYSTEM
ASS'Y P/N: 51140E1470-18-3 SHEET: 1

REF.	NEV.	DRAWING REF. DESIGNATION	FAILUNE HODE AND CAUSE	FAFLURE EFFECT ON END ITEM	HOWR / FUNC I/I RATFORALE FOR ACCEPTANCE CRITICALITY
3800		RIGIDIZE MECHANISH QTY-1 PART OF 51140E1472 -18-3	MODE: RIGIDIZE DRIVE TRAIN FAILS FREE.  CAUSE(S): (1) FRACTURED GEAR.	PAYLOAD CANNOT BE RIGIDIZED. IF A PAYLOAD IS RIGIDIZED IT MILL DERIGIDIZE AND THE CARRIAGE WILL EXTEND UNDER LOM APPLIED LOADS. ARM WILL STAY LIMP OWNING AUTO LAPIUHL SEU. WORST CASE UMCOMMANDED DERIGIDIZE. CREW ACTION REQUIRED. REDUNDART PATHS REMAINING M/A	HATERIALS SELECTION AND USAGE CONFORMS TO SPAR-SG. 368 WHICH IS EQUIVALENT TO THE MASA MATERIALS USAGE REQUIREMENTS.  THE STRUCTURAL ANALYSIS CONDUCTED ON THE EMD EFFECTOR PER SPAR-IR. 1531. CONFORMED A POSSITIVE MARGIN OF SAFETY FOR ALL END EFFECTOR PARTS AND CEARS. THE MARGIN OF SAFETY FOR ALL ULTIMATE STRENGTH MEURS) INCOMPORATES A FACTOR OF SAFETY OF 1.4 AGAINST LIMIT COAD. AS SPECIFIED IN SPAR-SG. 392.  A MEGATIVE MANGIN DUES NOT INCESSABILY IMPLY BREARAGE OF THE PART, RATHER IT IMPSCATES THAT A LIMITING STRESS LEVEL ESTABLISHED BUT THE FACTOR OF SAFETY, HAS BEEN EXCEEDED.  THE MARGIN OF SAFETY FOR VIEED STRENGTH SEVELDED EMPLOYS A FACTOR OF SAFETY OF 1.0 ACAIMST LIMIT LOAD. AS SPECIFIED IN SPAR-SG. 392. TABLE IT A LISTS MARGINS OF SAFETY FOR SAMS STRUCTURAL COMPONENTS.  A FATIGUE ANALYSIS WHICH SHOWS INDIFINITE LIFE HAS BEEN PERFORMED ON THE GEARS AND MECHANICAL FASTENERS AND A FRACTURE ANALYSIS WHICH SHOWS LIVES GREATER THAN 424 MISSIONS HAS BEEN ANALYSIS WHICH SHOWS LIVES GREATER THAN 424 MISSIONS HAS BEEN ANALYSIS WHICH SHOWS LIVES GREATER THAN 424 MISSIONS HAS BEEN ANALYSIS WHICH SHOWS LIVES GREATER THAN 424 MISSIONS HAS BEEN ANALYSIS WHICH SHOWS LIVES GREATER THAN 424 MISSIONS HAS BEEN ANALYSIS WHICH SHOWS LIVES GREATER THAN 424 MISSIONS HAS BEEN ANALYSIS WHICH SHOWS LIVES GREATER THAN 424 MISSIONS HAS BEEN ANALYSIS WHICH SHOWS LIVES GREATER THAN 424 MISSIONS HAS BEEN ANALYSIS WHICH SHOWS HAS BEEN ANALYSIS HAS BEEN AND CONTROLED BY THE FOLLOWING CONTEXT, IS A STRESS INDICATOR AND IS GIVEN BY THE FOLLOWING CONTEXT, IS A STRESS IND

AMED	BY:	NA MC	SUPERCEDING	DATE:	04 OCT 07	APPROVED	87;

•				
			·	
	•			
			·	
-				
			_	

PROJECT: SRMS ASS'Y MOMENCLATURE: END EFFECTOR

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/N: STITAGETATO-TE-1 SHEET: 2

THEA NAME OTY & FAILURE HODE FAILURE EFFECT HOUR FUNC.  ON 1/1 RAT  DESIGNATION CAUSE END ITEM CRETICALITY	FIGNALE FOR ACCEPTANCE
FAILS FREE.  SI 140E 1472 -18-3  CAUSE(S): (1) FRACTURED GEAR.  CARRIAGE HILL CARRIAGE CARR	THE TOTAL TESTING CONSISTED OF THE STAND DURATION - REFERENCE TABLE 7  MS - 3 AXES (& DIRECTIONS)  I DEGREES C TO -36 DEGREES C (& CYCLES)  ( 10==6 TORM  AS DEGREES C MAINTAINED FOR 6 HRS)  IEES C TO JO DEGREES C IN 16 HRS)  IS 740 HRS.  -461A AS MODIFIED BY SL-C-0002 (TEST  103. CSD1, CSD2, CSD6, RE02 (M/B))  SS AND LOAD TEST

APPROVED BY: RMS/MECH - 133 DATE:

PROJECT: SRHS ASS'Y NOMENCEATURE: END EFFECTOR

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/N: SITHOCLEYO-18-3 | SHEET: 3

REV.	NAME QTY L DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT OM END 1TEM	1/1 RATIONALE FOR ACCEPTANCE CRITICALITY
1800	RIGIDIZE HECHANISH QTY-1 PART OF SI140E1472 -18-3	NODE: RIGIDIZE DRIVE TRAIN FAILS FREE.  CAUSE(S): (1) FRACTURED GEAR.	PAYLOAD CANNOT BE RIGIDIZED. IF A PAYLOAD IS RIGIDIZED IT WILL DERIGIDIZE AND THE CAMBIAGE WILL EXTEND UNDER LOW APPLIED LOADS. ARM WILL STAY LIMP DURING AUTO CAPTURE SEQ. WORST CASE UNCOMMANDED DERIGIDIZE. CREW ACTION REQUIRED. REDUNDANT PATHS REHAINING M/A	UNITS ARE HANDFACTIRED UNDER BOCUMENTED QUALITY CONTROLS.  THESE CONTROLS ARE EXERCISED THROUGHOUT DESIGN PROCUREMENT, PLANNING, RECEIVING, PROCESSING, FABRICATION, ASSEMBLY, TESTING AND SHIPPING OF THE UNITS, MANDATORY INSPECTION POINTS ARE EMPLOYED AT VARIOUS STACES OF FABRICATION ASSEMBLY AND TEST, GOVERNMENT SOURCE INSPECTION IS INVOKED AT VARIOUS CONTROL LEVELS.  RECEIVING INSPECTION VERIFIES THAT THE HARDWARE RECEIVED IS AS IDENTIFIED IN IME PROCUMENENT DUCKHEMS. HAIR NO DAMAGE HAS OCCURRED DURING SHIPPENT, AND THAT APPROPRIATE DATA MAS BEEN RECEIVED UNION SHIPPENT, AND THAT APPROPRIATE DATA MAS BEEN RECEIVED UNION SHIPPENT, AND THAT APPROPRIATE DATA MAS BEEN RECEIVED UNION SHIPPENT, AND THAT APPROPRIATE DATA MAS BEEN RECEIVED UNION SHIPPENT, AND THAT APPROPRIATE DATA MAS BEEN OCCURRED DURING SHIPPENT, AND THAT APPROPRIATE DATA MAS BEEN RECEIVED UNION SHEAT AND THAT APPROPRIATE DATA MAS BEEN RECEIVED UNION SHEAT AND ALL AND THAT INVOLUTE OF AN INSPECTION BEFORE GEAR LUBRICATION AND RUN. IN A COMPOSITE ERROR GEAR CHECKER IS USED TO VERIFY THAT INVOLUTE FORM INFECTION SHOULDE.  GEAR INSPECTION BEFORE GEAR LUBRICATION AND RUN. IN A COMPOSITE ERROR GEAR CHECKER IS USED TO VERIFY THAT INVOLUTE FORM INFECTION SHOULDED.  GEAR INSPECTION BEFORE GEAR LUBRICATION AND RUN. IN A COMPOSITE ERROR GEAR CHECKER IS USED TO VERIFY THAT INVOLUTE FORM INFECTION OF CRACKS OF IN THE CASE OF A LUBRICATION, CEARS ARE VISUALLY INSPECTED.  FOLLOWING HEAT TREATHERY STEEL PARTS (E.G. GEARS) ARE SUBLICETED TO A HAGNETIC PARTICLE INSPECTION FOR CRACKS OF IN THE CASE OF ALUBRIUM PARTS (E.G. HOUSINGS) ARE DIFFERED TO A HADDISHAM AND THAT AREATHERY STEEL PARTS. (E.G. GEARS OR HOUSINGS IS SUBJICTED TO DUE PERETRANTS, MELDING FEARS OR HOUSINGS IS SUBJICTED TO PERETRANTS, MELDING FEARS OR HOUSINGS IS SUBJICTED TO THE PARTS ARE CORRECT PRIOR TO ASSEMBLY AND TRACERGULLY! INSPECTION OF LOOKING, WITHESSING OF TORQUIME AND APPLICATION OF TORQUE ESTING HORD FOR THE  INSPECTION TO AS DESIGN ETC. (HANDATORY INFECTION FOR TORTH)  A TEST READINGS REV

PROJECT: SRMS
ASS'Y MONENCLATURE: END EFFECTOR

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/H: STIJBETITO-IE 3 SHEET: 4

RCF.   REV.   DRAWING MÉF.	LURE MODE FARLURE EFFECT HOWA / FUNC.  AND ON I/I RATIONALE FOR ACCEPTANCE  CAUSE END ITEM CRATICALITY
OTY-1 DRIV PART OF FAIL S1140E1472 -18-3 1 CAUS	AND THERMAL-VAC TESTING (SPAR/GOVERNMENT REP MANDATORY  IF A PAYLOAD IS INSPECTION POINT)  INSPECTION POINT)  INSPECTION THE INTEGRATION THE INTEGRATION OF MECHANICAL ARM  INSPECTIONS AND THE SUBASSEMBLIES AND THE FLIGHT CABIN EQUIPMENT TO FORM THE SAMS.  INSPECTIONS ARE PERFORMED AT EACH PHASE OF INTEGRATION MICH  EXTEND UNDER INCLUDES GROUNDING CHEEKS HAND MADING CHE

PREPARED BY: WWG SUPERCEDING DATE: 06 OCT 87

APPROVED BY: \_\_\_\_\_RMS/MECH - 135

PREPARED BY: MY

PROJECT: SAMS ASS'Y MONENCEATURE: END EFFECTOR

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/R: STIGOETE70-18:] SHEET: S

PEF.	AEV.	NAME OTY B DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END-ITEM	HDMR / FUNC.  I/I RATIONALE FOR ACCEPTANCE  CRITICALITY
3800	1	DESIGNATION  RIGIDIZE RECHANISH OTY-1 PART OF S1140E1472 -16-3	CAUSE  MODE: MIGIDIZE BRIVE TRAIM FAILS FREE.  CAUSE(S): (I) FRACTURED GEAR.		CRITICALITY  FAILURE MISTORY  THERE MAYE BEEN NO FAILURES ASSOCIATED MITH THIS FAILURE MUDE ON THE SRMS PROGRAM.
		:			

APPROVED BY:

SUPERCEDING DATE: 06 OCT 07

RMS/MECH - 136

PROJECT: SANS ASS'Y MONEHICLATURE: END EFFECTOR

SYSTEM: MECHANICAL ARM SUBSYSTEM
ASS'Y P/M: STINOTINFO-TE 3 | SHEET: 6

PEF.	REV.	DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOUR / TURG.  1/5  CRITICALITY  RATIONALE FOR ACCEPTANCE
7608		RIGIDIZE NECHANISH QTY-I PART OF S1140C1472 - (6-3	MODE: BIGIDIZE BRIVE TRAIN FAILS FREC.  CAUSE(S): (1) FRACTURED GEAR.	PATLOAD CANNOT OF RIGIDIZED IF A PATLOAD IS RIGIDIZED IF WILL DERIGIDIZE AND THE CARRIAGE WILL EXTEND UNDER LOW APPLIED LOADS. ARM WILL STAY LIMP OURING AUTO CAPTURE SEU. MORST CASE UNCOMMANDED DERIGIDIZE. CREW ACTION REDUNDAME PATHS REMAINING M/A	PAYLOAD WILL BE DERIGIDIZED WITH NO OPERATOR COMMAND. IF THIS DECURS WHILE THE ARM IS BEING DRIVER. THE PAYLOAD WILL TARE AND UNEMPECTED TRAJECTORY. ARM WILL PREMAIN LIPP UNTIL EE MODE SWITTURNED TO DIF DURING ANTO CAPTURE SEQUENCE.  CREW ACTION  RELEFASE PAYLOAD AND MANEUVER ARM AND ORBITER AWAY FROM PAYLUAD.  CREW HIPL BE, IRRAINED TO DETECT OFF MOMINAL EE OPERATIONS AND TO MANEUVER THE ORBITER AMAY FROM A FREE FLYING PAYLOAD AT AMY TIME OURING ARM OPERATIONS.  MISSION CONSTRAINT  SPEC OPERATE UNDER VERNIER RATES WITHIN TO FT OF STRUCTURE. THE OPERATION WIST DE ABLE TO DETECT THAT THE ARM/PAYLOAD IS RESPONDING PROPERTY TO COMMANDS VIA WITHOUT ARM/PAYLOAD SY SERVENDING PROPERTY TO COMMANDS VIA WITHOUT ARM/PAYLOAD SYLE SOUTH AND OPERATIONS.  EE RODE SWITCH SET TO OFF IMPLIANTELY AFTER SPEC ORIVE TIME HAS ELAPSED.  SCREEN FAILURES  N/A  OMBSD OFFLINE  PERFORM NAMUAL CAPTURE/RIGIDIZE.  OMRSD OWLINE INSTALLATION  ROME  OMRSD OWLINE INSTALLATION
					VERIFY COURTET SI AC TIMING-EXTEND TO RIGIDIZE.